

Giant Resource Recovery-Sumter, Inc.
Acceptable Waste Codes

F001	D001	Ignitable Waste	D024	m-Cresol
F002	D004	Arsenic	D025	p-Cresol
F003	D005	Barium	D026	Cresol
F005	D006	Cadmium	D027	1,4-Dichlorobenzene
	D007	Chromium	D028	1,2-Dichloroethane
	D008	Lead	D029	1,1-Dichloroethylene
	D009	Mercury	D030	2,4-Dinitrotoluene
	D010	Selenium	D031	Heptachlor (and its Epoxide)
	D011	Silver	D032	Hexachlorobenzene
	D012	Endrin	D033	Hexachlorobutadiene
	D013	Lindane	D034	Hexachloroethane
	D014	Methoxychlor	D035	Methyl Ethyl Ketone
	D015	Toxaphene	D036	Nitrobenzene
	D016	2,4-D	D037	Pentachlorophenol
	D017	2,4,5-TP (Silvex)	D038	Pyridine
	D018	Benzene	D039	Tetrachloroethylene
	D019	Carbon Tetrachloride	D040	Trichloroethylene
	D020	Chlordane	D041	2,4,5-Trichlorophenol
	D021	Chlorobenzene	D042	2,4,6-Trichlorophenol
	D022	Chloroform	D043	Vinyl Chloride
	D023	o-Cresol		

D002 Can be accepted as an additional waste code to describe an "F" waste.